

ADJUSTING THE FRICTION WITH PRECI-VERTIX AT M
--

1. Use only the **1829** screw-driver.
2. Take the prosthesis and carefully tighten the **1828** activating screw to increase the friction.
Turn in the opposite direction to decrease the friction.
3. Repeat this procedure until the required friction is attained.