

REPLACING THE FRICTION PART WITH PRECI-VERTIX AT M

1. Use only the **1829** screw-driver.
2. Take the prosthesis and carefully loosen the **1828** activating screw until the **1822** yellow friction part can be easily removed.
3. Apply a new **1822** plastic friction part and tighten the screw to the stop.
4. Adjust until the required friction is attained (see INFO 127).